

## Radio fascia 381200-04

For vehicles Mitsubishi Lancer mit MMCS System  
OEM Panel number(8002A541XA)

You can find detailed information about vehicle models, connection and functions in our web store at <https://shop.acvgmbh.de>. Enter the article number in the search field and click on Downloads.

### DISCLAIMER

The information contained in this document may differ without notice if changes are made to the product(s). These instructions are based on documented data and tests. ACV GmbH cannot be held responsible for any damage caused by the installation of this product in the event of modifications to vehicles (e.g. software updates, hardware replacement). Installation should only be carried out by a qualified specialist.



1. Remove the screws on the right and left of the panel




5. Attach the metal brackets to the retrofit radio and connect all cables  
Install the unit in the dashboard



2. Release the cover



6. Install the radio panel with the trim frame again  
mount the rest in reverse order to complete the installation



3. Remove the switch unit



4. Remove the OEM radio